


ChipsetINF_10394718012_1.zip

Vulnerability analysis verdict: PASS / Information leakage: PASS



Identified 3rd party components

- Driver Install Frameworks API (DIFxAPI) 2.1

Intel.Deployment.ChipsetWiX.CustomAction 3.1.7.202

Intel.Tools 3.1.7.202

Intel.Tools.DeviceManager 3.1.7.202
- Intel® Chipset Device Software 10.1.19949.8616

Windows Installer XML Toolset 3.14.1.8722

WixToolset.Dtf.WindowsInstaller 3.14.1.8722

Missing exploit mitigation techniques

- Driver Install Frameworks API (DIFxAPI) 2.1**

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCADll/DIFxAPI.dll

authenticcode-no-codesigning-attribute

no-control-flow-enforcement

no-enforced-code-integrity
- ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCADll/DIFxAPI.dll

authenticcode-no-codesigning-attribute

no-enforced-code-integrity
- ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCADll/DIFxAPI.dll

authenticcode-no-codesigning-attribute

no-control-flow-enforcement

no-enforced-code-integrity
- ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCADll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll
authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DIFxAPI.dll

authenticode-no-codesigning-attribute
no-enforced-code-integrity

Intel.Deployment.ChipsetWiX.CustomAction 3.1.7.202

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

no-buffer-security-check
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/ChipsetWiX.CustomAction.dll

- no-buffer-security-check
- no-control-flow-guard
- no-enforced-code-integrity

Intel.Tools 3.1.7.202

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

- no-buffer-security-check
- no-control-flow-enforcement

no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard

no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Intel.Tools.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Intel.Tools.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

Intel.Tools.DeviceManager 3.1.7.202

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/DeviceManager.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity

Intel® Chipset Device Software 10.1.19949.8616

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe

- no-control-flow-enforcement
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe

- no-control-flow-enforcement
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe

- no-control-flow-enforcement
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe

- no-control-flow-enforcement
- no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe

no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe
no-control-flow-enforcement
no-enforced-code-integrity

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe
no-control-flow-enforcement
no-enforced-code-integrity

Windows Installer XML Toolset 3.14.1.8722

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.
ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll
no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.
ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll
no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.
ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll
no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.
ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll
no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0
/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-NDA-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-PreSi-Server-BKC.zip/Apps/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616-Public-Server-MUP.zip/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chips etWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.Chips
etWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.Chips
etWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binar
y.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binar
y.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binar
y.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/NDA-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binar
y.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.Chip
setWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a0/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.Cab.dll

- no-buffer-security-check
- no-control-flow-enforcement
- no-control-flow-guard
- no-enforced-code-integrity
- no-high-entropy-aslr

ChipsetINF_10394718012_1.zip/Chipset-10.1.19949.8616.zip/Public-Server/SetupChipset.exe/SetupChipset.exe.cab/a1/Binary.ChipsetWiXCAdll/Microsoft.Deployment.Compression.dll

no-buffer-security-check
no-control-flow-enforcement
no-control-flow-guard
no-enforced-code-integrity
no-high-entropy-aslr

Details

Original filename	ChipsetINF_10394718012_1.zip
SHA1 checksum	4fc7dfd1a359a9e264cc68edb71ee886ccc42c99
Original file size	39.49 MB

Infoleak

Asymmetric keys:	0
AWS keys:	0
Custom pattern matches:	0
Emails:	0
HTTP authentication:	0
Image metadata:	0
IP addresses:	41
JSON web tokens:	0
MAC addresses:	0
OAuth tokens:	0
Passwords:	0
Shell history:	0
URLs:	0
Twilio keys:	0
Google cloud keys:	0
Facebook access tokens:	0