



Intel® Smart Sound Technology Driver

Release Notes: Raptor Lake Intel SST Release

October 2022

Revision 1.0

Intel Confidential



By using this document, in addition to any agreements you have with Intel, you accept the terms set forth below.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: <http://www.intel.com/design/literature.htm%20>

All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice.

This document contains information on products in the design phase of development. Do not finalize a design with this information. Revised information will be published when the product is available. Verify with your local sales office that you have the latest datasheet before finalizing a design.

Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See www.intel.com/products/processor_number for details.

Code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion or marketing of any product or services and any such use of Intel's internal code names is at the sole risk of the user.

Intel, Core, and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries.

Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license.

*Other names and brands may be claimed as the property of others.

Copyright © 2021 – 2022, Intel Corporation. All rights reserved.

Contents

1	Introduction	5
	1.1 Scope of Document	5
	1.2 System Requirements	5
	1.3 Acronyms and Terminology	5
2	Release Kit Summary	7
	2.1 Release Kit.....	7
	2.2 Kit Contents	7
3	Intel [®] SST Release Details	8
4	Intel [®] SST Release Highlights.....	9
5	Important Notes:	10
6	Known Issues	11
7	Closed Issues.....	12

Revision History

Revision Version	Revision History	Revision Date
0.1	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 6218	October 2021
0.2	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 6755	November 2021
0.3	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 6886	January 2022
0.4	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 7082	February 2022
0.5	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 7541	April 2022
0.6	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 7687	May 2022
0.7	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 7767	June 2022
0.8	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 7919	August 2022
0.9	<ul style="list-style-type: none">Intel® SST Raptor Lake Release 8050 HF	September 2022
1.0	<ul style="list-style-type: none">Intel® SST Alder Lake Release 8102	October 2022

1 Introduction

1.1 Scope of Document

This document provides release information about the Intel® Smart Sound Technology (Intel® SST) Driver. It covers Release Kit summary, Important Notes, Known and Closed Issues.

This document is intended for OEMs and ODMs that are validating the Intel® Smart Sound Technology Driver on Raptor Lake (RPL) platforms with Intel Audio DSP integrated

1.2 System Requirements

Intel® Smart Sound Technology Driver supports the following Intel CPU/Chipset:

- Raptor Lake Processors

Platform Support:

- Raptor Lake processor-based platforms with Intel Audio DSP integrated

Operating Systems support:

- Microsoft Windows* 10/11 64-bit

1.3 Acronyms and Terminology

Term	Description
ACPI	Advanced Configuration and Power Interface
BIOS	Basis Input/output System
BT	Bluetooth
DMIC	Digital Microphone
DSP	Digital Signal Processor
EA	Enrollment Application
FDK	Firmware Development Kit
FW	Firmware
HDA or HD-Audio	High Definition Audio
HFP	Hands-Free Profile

IHV	Independent Hardware Vendor
ISV	Independent Software Vendor
Intel® SST	Intel® Smart Sound Technology
IPR	Ingredient Planned Release
LP	Low power
MCP	Multi-Chip Package
MCPS	Million Clocks Per Second
MCS	Modern Connected Standby Platform
MR	Maintenance Release
Non-MCS	Non-Modern Connected Standby Platform
OED	Offload Engine Driver
OS	Operating System
PC	Production Candidate
PCH	Platforms Controller Hub
PR	Planned Release
PV	Production Version
RPL	Raptor Lake
RS	Redstone
RVP	Reference Validation Platform
SUT	System under test
TBD	To be determined
TH	Threshold
ULT	Ultra-Thin
WOV	Wake on Voice

2 *Release Kit Summary*

2.1 Release Kit

Kit Name: Intel® Smart Sound Technology Driver Raptor Lake Release

Supported OS: Windows* 10/11 64-bit

Version: 10.29.00.8102

2.2 Kit Contents

The contents of this release kit include:

- Drivers
 - DSP Firmware
 - Topology
 - WOV Artifacts
 - IntcAudiobus – Intel SST Audio Bus Driver for HD-A I/F
 - IntcOED – Intel SST Offload Engine Driver
 - Detection Verification Driver
 - Intel® DMIC driver
 - Intel® Bluetooth Audio Driver
 - Intel® USB Audio Driver
 - Intel® SST I2S Driver
 - Intel® Soundwire Bus Driver
 - Intel® Soundwire Driver
- Module Version
 - Intel WOV version 2.5.900.20_986
 - Intel Audio Service version 01.00.2391.00
- Apps
 - Intel® Audio Service: Part of Intel SST OED Installation.
- Intel® Smart Sound Technology Driver – Release Notes



3 *Intel® SST Release Details*

3.1 Intel® Smart Sound Technology Collaterals

Please refer to following Intel® SST collaterals for Intel® SST bring-up, validation and debug guidance.

Doc Number & Location	Doc Number & Location
Intel® Smart Sound Technology Driver - Bring-Up Guide	Included in every SST release package Intel CDI Doc #613171
Intel® Smart Sound Technology Customer - Validation and Debug Guide	Intel CDI Doc #613651

3.2 Platform Best Known Configuration

Please refer to Raptor Lake BKC Release.

3.3 Focused Testing Area

Please refer to the Intel® Smart Sound Technology Validation and Debug Guide on Intel® CDI (Document # 613651) for the test cases to test the following Intel® SST features.

For Desktop Processors:

- HD-Audio Playback
- HD-Audio Capture
- Digital Microphone Capture

For Mobile Processors:

- HD-Audio Playback
- HD-Audio Capture
- Digital Microphone Capture
- Intel® Wake on Voice - Contact Intel FAE or Intel® SST AE for more details.
- Post-processing - Contact Intel FAE or Intel® SST AE for more details.
- Pre-processing - Contact Intel FAE or Intel® SST AE for more details.

4 **Intel® SST Release Highlights**

Intel® SST Features		Highlights
Intel® Audio Service	Intel® Audio Service	Intel® Audio Service installer is provided for to support Intel WOV via Intel Speech Pin
Intel® SST Post-Processing		Post processing IP ISVs will integrate their audio IP FW modules using the Intel audio FDK tool and provide their FW to the IHV's for final audio driver and FW integration for OEM customer platforms.
Intel® SST Pre-Processing	Intel Preprocessing IP	Intel Preprocessing FW is included. Note: Pre-processing IP ISVs will integrate their audio IP FW modules using the Intel audio FDK tool and provide their FW to the IHV's for final audio driver and FW integration for OEM customer platforms.
HD Audio Interface	NA	HD Audio interface support has been implemented and included in CFL Intel® SST Release. Disclaimer: To test HD-A interface, a codec driver from audio codec vendor is required. Please contact your codec vendor to obtain the driver supporting this feature.
I2S Interface	NA	I2S Interface support has been implemented and included in the Release. Disclaimer: To test I2S interface, a codec driver from audio codec vendor is required. Please contact your codec vendor to obtain the driver supporting this feature.
SoundWire Interface	NA	SoundWire interface support has been implemented and included in CFL Intel® SST Release. Disclaimer: To test SoundWire interface, a sound wire driver from SoundWire device vendor is required. Please contact your sound wire device vendor to obtain the driver supporting this feature.



5 *Important Notes:*

6 *Known Issues*

Issue #	Description
---------	-------------

7 Closed Issues

Sighting	Title	Fixed version
22015702615	Mute button for mic does not work for some specific type-C headset.	8102
22015740850	Some Type-C headphone Mic cannot record with 7919.	8102
22015477120	Audio icon show "x" after fast close/open lid with Cortana and Alexa enabled.	8102
22015688717	[SDW] HLK failed: Modern Standby Voice Activation Power Test on AC/DC-power.	8102
15012082984	No SW Drips when ACA is running.	8102
22015939833	System show up "Your microphone is not working" after resume from S4 during Teams call.	8102
22015642363	Speaker no sound after playing the video for a while on the USB-Codec device.	8102
22015172239	Audio from USB device cut during VoIP call.	8102
22015510184	Speaker error after resuming from S4 and plug out the USB headset.	8102
22015585034	ISST OED YB after resuming system from MS while playing online video and enabling WoV in the background.	8102
22015841168	USB audio device cannot work after updating Intel Graphics driver	8102
22015570204	[SDW] DUT will show BSOD(error code: 0xdeadbeef) during the audio driver uninstall and install process.	8050
22015750110	ISV module may not work properly with v7919.	8050
22015468262	ACA module init fail when load with 3 rd party's module.	8050
22015514494	Music player freeze and USB headset hang after wake from S4.	8050
15011627170	WoV don't have gain if DUT not record before.	8050
22015550870	[SDW] HLK: System - PNP (disable and enable) with IO Before and After (Reliability) test failed due to unexpected reboot.	8050
22015138970	Recorded video via camera app then click camera roll will show fail message.	7919
22015102787	Media player show error code after adjusting volume from task bar.	7919
22015099238	Music still outputs from speaker after plug in type-c earphone.	7919
22015046864	BT device can't remove successfully when the Bluetooth headset is connected	7919
22014104819	The advance page and spatial page will disappear after unchecking the HW acceleration of the USB headset in the sound control panel.	7919
22014861643	The Sound icon show X in system tray with PA enabled and doing WU.	7919
22015267012	BSOD 0x9F while running restart stress test with AC/DC cycle.	7919
18021993032	Windows Media Player pops up error message "An audio device was disconnected or reconfigured" when insert 3.5mm Jack device for the first time.	7767
15010805358	Some USB headsets cannot work when connect to the USB hub.	7767
18020606784	Create one build for ADL and RPL	7687



14016116673	[HLK] Audio Codec - KS Topology Test fail	7541
18020354732	BSOD caused by IntcOED.sys BugCheck = C4 when uninstalling the driver	7541
18019823520	[UAOL]Voice Recorder playback only on first channel - Voice Recorder Compatibility	7082
18019047535	[IAS] Add RPL-P HWID	6886
18018875109	Add RPL-P HWID	6755
18018702891	Bsod IntcOED.sys (IntcOED!OELogListener::FreeBuffer+cc), BugCheck C4, FAILURE_BUCKET_ID: 0xc4_b9_VRF_IntcOED!OELogListener::FreeBuffer	6755